


## PST-1

**POWER SUPPLY** 



- 1. Dimensions are shown in mm & inch
- 2. Weight: approx. 265~280g (Exclude the input cord)
- 3. Optional output connector.


- 4. Operating Temperature: 0 to 70°C
- 5. Derate linearly from 100% load at 40°C to 50% load at 70°C

<u>PLEASE NOTE:</u> Please with the super power supply PST-1 supplied use only the power cord supplied or one strictly certified for UL, CE, and all local necessary certifications.

## **CONNECTING THE POWER SUPPLY ADAPTER**

Use only the original GOLD NOTE AC adapter to power the turntable to ensure the correct functioning.

<u>PLEASE NOTE:</u> Before plugging the adapter in to the AC make sure the connector is plugged into the turntable.







ogoldnote\_italy





■ Gold Note

Akamai S.r.l. service@goldnote.it www.goldnote.it